UNITED STATES DISTRICT COURT DISTRICT OF NEW HAMPSHIRE

U.S. DISTRICT COURT DISTRICT OF NEW HAMPSHIRE

SEP 3 0 2013

		FILED
KURT WEST,))	
Plaintiff,))	
v.) Civil Action No. 1:10-cv-00214-JL	
BELL HELICOPTER TEXTRON, INC., GOODRICH PUMP AND ENGINE CONTROL SYSTEMS, INC., AND ROLLS-ROYCE CORP.,))))	5
Defendants.))	

PLAINTIFF'S EXHIBIT LIST (SEPTEMBER 9, 2013 UPDATE)

Plaintiff Kurt West submits the following list of exhibits for use at trial:

NUMBER	(ID)?	DESCRIPTION
1		Bow PD Photograph 1
2		Bow PD Photograph 2 🗸
3		Bow PD Photograph 3
4		Bow PD Photograph 4
5		Bow PD Photograph 5
6	(ID)	GPECS ECU Schematics 1
7	(ID)	GPECS ECU Schematics 2
8	(ID)	GPECS ECU Schematics 3
9	(ID)	GPECS ECU Schematics 4
10	(ID)	GPECS ECU Schematics 5
11	(ID)	GPECS ECU Schematics 6
12	(ID)	GPECS ECU Schematics 7
13	(ID)	GPECS ECU Schematics 8
14	(ID)	GPECS ECU Schematics 9
15	(ID)	GPECS ECU Schematics 10
16	(ID)	GPECS ECU Schematics 11
17	(ID)	GPECS ECU Schematics 12
18	(ID)	GPECS ECU Schematics 13
19	(ID)	GPECS ECU Schematics 14
20	(ID)	GPECS ECU Schematics 15

	21	(ID)	GPECS ECU Schematics 16
Γ	22	(ID)	GPECS ECU Schematics 17
	23	(ID)	GPECS ECU Schematics 18
	24	(ID)	GPECS HMU Schematic
	24A	(ID)	GPECS HMU Schematic - McBrine Ex. 18
F	25	, , , ,	West Incident Photograph 1
Ī	26		West Incident Photograph 2
Ì	27		West Incident Photograph 3
Ī	28		West Incident Photograph 3
919	<u>~ 29</u>	(38)	West Incident Photograph (4)
11 ,	30		
	20		
			7
4/2	•	Dec	West Incident Photograph (5)
Ī	31		West Incident Photograph 6
	32		West Incident Photograph 7
Ī	33	(ID)	West Incident Photograph 8
1	34	(ID)	West Incident Photograph 9
Ī	35	(ID)	West Incident Photograph 10
Ī	36		West Incident Photograph 11
ļ	37	(ID)	West Incident Photograph 12
-	38	(ID)	West Incident Photograph 13
Ì	39	(ID)	West Incident Photograph 14
ļ	40	(ID)	West Incident Photograph 15
ŀ	41	(ID)	West Incident Photograph 16
}	42	(ID)	West Incident Photograph 17
<u> </u>	43	(ID)	West Incident Photograph 18
}	44	(ID)	West Incident Photograph 19
}	45	(ID)	West Incident Photograph 20
ŀ	46	(ID)	West Incident Photograph 21
}	47	(ID)	West Incident Photograph 22
-	48	(ID)	West Incident Photograph 23
ŀ	49	(ID)	West Incident Photograph 24
	50	(ID)	West Incident Photograph 25
	51	(11)	Trauma Center West Records 1
			Trauma Center West Records 2
ļ	50		Trauma Center West Records 2 Trauma Center West Records 3
	53 V	ļ	
	54 🗸		Trauma Center West Records 4

55 ,/	1	Trauma Center West Records 5
56		Trauma Center West Records 6
57 /		Trauma Center West Records 7
58		Trauma Center West Records 8
59 🗸		Trauma Center Receipt 1
60 /		Trauma Center Receipt 2
61		Trauma Center Receipt 2 Trauma Center Receipt 3
$\frac{61}{62}$,	Trauma Center Receipt 4
$\frac{62}{63}$		Trauma Center Receipt 5
	,	Trauma Center Receipt 6
64 ✓	(ID)	Trauma Center Receipt 7
66	(ID)	Australia Receipt 1
67	(ID)	Australia Receipt 2
68	(ID)	Australia Receipt 3
69	(ID)	Australia Receipt 4
70	(ID)	Australia Receipt 5
71	(ID)	Australia Receipt 6
72	(ID)	Australia Receipt 7
L	(ID)	Australia Receipt 8
74	(ID)	Australia Receipt 9
75	(ID)	Australia Receipt 10
76	(ID)	Australia Receipt 11
77	(ID)	Australia Receipt 12
78	(ID)	Australia Receipt 13
79	(ID)	Australia Receipt 14
80	(ID)	Australia Receipt 15
81	(ID)	Australia Receipt 16
82	(ID)	Australia Receipt 17
83	(ID)	Australia Receipt 18
84	(ID)	Australia Receipt 19
85	(ID)	Australia Receipt 20
86	(ID)	Australia Receipt 21
87	(ID)	Australia Receipt 22
88	(ID)	Australia Receipt 23
89	(ID)	Australia Receipt 24
90	(ID)	Australia Receipt 25
91	(ID)	Australia Receipt 26
92	(ID)	Australia Receipt 27
93	(ID)	Australia Receipt 28
94	(ID)	Australia Receipt 29
95	(ID)	Australia Receipt 30
96	(ID)	Australia Receipt 31
97	(ID)	Australia Receipt 32
98	(ID)	Australia Receipt 33
99	(ID)	Australia Receipt 34

Γ	100	(ID)	Australia Receipt 35
ľ	101	(ID)	Australia Receipt 36
F	102	(ID)	Australia Receipt 37
ľ	103	(ID)	Byrne Medical Records 1
	104	(ID)	Byrne Medical Records 2
-	105	(ID)	Concord Hospital Medical Records 1
	106	(ID)	Concord Hospital Medical Records 2
	107	(ID)	Concord Hospital Medical Records 3
-	108	(ID)	Dartmouth Hitchcock Medical Records 1
	109	(ID)	Dartmouth Hitchcock Medical Records 2
	110	(ID)	Dartmouth Hitchcock Receipt 1
	111	(ID)	Dartmouth Hitchcock Receipt 2
ľ	112	(ID)	Dartmouth Hitchcock Receipt 3
	113	(ID)	Lahey Medical Records 1
	114	(ID)	Lahey Medical Records 2
F	115	(ID)	Lahey Medical Records 3
-	116	(ID)	Lahey Medical Records 4
ļ	117	(ID)	Lahey Medical Receipt 1
	118	(ID)	Lahey Medical Receipt 2
F	119	(ID)	Lahey Medical Receipt 3
Ī	120	(ID)	Lahey Medical Receipt 4
	121	(ID)	Lahey Medical Receipt 5
Ī	122	(ID)	Lahey Medical Receipt 6
	123	(ID)	Lahey Medical Receipt 7
ľ	124	(ID)	Lahey Medical Receipt 8
	125	(ID)	Nashua West Adult Medical Records 1
	126	(ID)	Nashua West Adult Medical Records 2
	127	(ID)	SNHMC Medical Records 1
	128	(ID)	SNHMC Medical Records 2
	129	(ID)	SNS Procedure Photograph 1
	130	(ID)	SNS Procedure Photograph 2
	131	(ID)	2003.05.14 - Email re Goodrich Systemic Issues
0/33	131A	(SAR)	2003.05.14 - Email re Goodrich Systemic Issues - Ronan Ex. 22
-,, [132	(ID)	2004.05.05 - Email re Removals Database Status
Γ	132A	(XXX)	2004.05.05 - Email re Removals Database Status - Ronan Ex. 17
	133	(ID)	2004.07.07 - Email re Compliance with CEB 73-6036
	133A	(XKQ)	2004.07.16 Email Chain re July Rep Update - Ronan Ex. 6
	134	(ID)	2009.01.23 - Email from Ronan re West Incident Recorder Download
	134A	(ID)	2009.01.23 Attachment to Ronan email to Riser
	134B		2009.01.23 - Email from Ronan re West Incident Recorder Download -
9/32		(SQ)	Ronan Ex. 19
Q/Y	5 135	(30)	2009.03.04 - Ronan email re engine test
,	135A	(ID)	McBrine 2012.03.27 Ex. 3
0/33 0/33	135B	() (X ())	2009.03.04 - Ronan email re engine test - Ronan Ex. 20
	135C	(ID)	2009.03.04 Ronan email re engine test - Riser Ex. M

	136		136 CEB 73-6036 Rev. 3
2 al	136C)XX)	CEB 73-6036 Rev. 3 - Ronan Ex. 4
y/m	137	(ID)	Colonics Receipts - Celeste Day Spa
-	138	$\frac{\text{(ID)}}{\text{(ID)}}$	Colonics Receipts - Clough Colon Hydrotherapy
	139	(ID)	Colonics Receipts - Gardens Wellness
	140	(ID)	Colonics Receipts - Groton Dental Wellness Spa
	141	(ID)	Colonics Receipts - ISIS Holistic Clinic
	142	(ID)	Colonics Receipts - Lifetime Health and Consulting
	143	(ID)	Colonics Receipts - North East Lifestyle Med
	144	(ID)	Rolls Royce Engine Investigation Report on West Incident
	144A	(12)	Rolls Royce Engine Investigation Report on West Incident - Riser Ex.
İ	1771	(ID)	K
	145	(12)	2009.02.03 - Email re: West IR Data
-	145A	(ID)	2009.02.03 Email re West IR Data - Riser Ex. H
	146	(ID)	ASB 407-99-28
-	146A	(ID)	ASB 407-99-28 - Stuntzner Ex. 4
	147	(ID)	Bell Accident Investigation Record for West Incident
	147A		Bell Accident Investigation Record for West Incident - Stuntzner Ex.
4117	17/21	(Dee)	17
	148	(ID)	CSL 6100
	148A	(ID)	CSL 6100 - Stuntzner Ex. 8
211	149	(MX)	Photograph of West Cockpit - Stuntzner Ex. 19
3/1/	150	(ID)	2009.01.30 - Email Chain re: West IR Data
6.111	150A	(XXI)	2009.01.30 - Email Chain re: West IR Data - Stuntzner Ex. 16
914	151	(ID)	Scherer Record 1
	152	(ID)	Scherer Record 2
	153	(ID)	Scherer Record 3
	154	(ID)	Scherer Record 4
	155	(ID)	Scherer Record 5
	156	(ID)	Scherer Record 6
	157	(ID)	Scherer Record 7
. +	158	LID	Scherer Record 8
;	159	(ID)	Scherer Record 9
	160	(ID)	Scherer Record 10
	161	(ID)	Scherer Record 11
	162	(ID)	Scherer Record 12
	163	(ID)	Scherer Record 13
	164	(ID)	Scherer Record 14
	165	(ID)	Scherer Record 15
	166	(ID)	Scherer Record 16
	167	(ID)	Scherer Record 17
	168	(ID)	Scherer Record 18
	169	(ID)	Scherer Record 19
	170	(ID)	Scherer Record 20
	171	(ID)	Scherer Record 21

Г	172	(ID)	Scherer Record 22
-		(ID)	
}	173	(ID)	Scherer Record 23
ł	174	(ID)	Scherer Record 24
-	175	(ID)	Scherer Record 25
ļ	176	(ID)	Scherer Record 26
,	177	(ID)	Scherer Record 27
]	178		Arrow Logbook Entries
1	179		Rolls Royce Engine Assembly Inspection Records 7
	180		Rolls Royce Engine Assembly Inspection Records 9
	181		Rolls Royce Engine Assembly Inspection Records 11
ļ	182		Rolls Royce Engine Assembly Inspection Records 14
	183	(ID)	2010.10.28 - FAA Airworthiness Directive Compliance Report
	184		2009.12.03 - West Engine Service Accessory Record
	185		2009.12.11 - Authorized Release Certificate for West HMU
	186		2009.11.12 - Rolls Royce Engine Services Component Condition
		(ID)	Report
L	187		2009.10.22 - Service Record for West Compressor Assembly
	188		2009.10.22 - Assembly Record for West Compressor Assembly
	189		2009.11.12 - Overhaul Diagram for West Compressor Assembly
	190	(XX)	2010.10.28 - FAA Airworthiness Directive Compliance Report
	191	(XXX)	Bell Final Technical Data Status Related to West Helicopter
	192		2005.01.10 - Repair and Alteration Report for Skymap Tracker
	193		2004.03.25 - Major Repair and Alteration Report
Ī	194		2009.08.17 - Email Chain re: Return of Accident HMU and ECU
Γ	195	(ID)	2009.08.14 - Email Chain re: Release of West ECU and HMU
	196	(ID)	2009.04.30 - Email Chain re: Salvage Award Letter
Ī	197	(ID)	West Incident Incident Recorder Plot Color
	198		2008.12.22 - Altitude Data for Accident Flight
	199		Business Cards of Investigation Parties
	200	(ID)	NTSB Draft Factual Report West Incident
	201		2009.01.21 - Stuntzner Interview Notes re: West, Newcomb, and
			Sharkey
	202		2009.01.21 - ECU Download from West Helicopter
	203		Incident Recorder Data from West Helicopter
	204		2009.01.22 - Email from Stuntzner re: West Investigation
0/23		(3884)	2009.01.29 - Email Chain re Accident Investigation
~\\\	206	F /	2009.01.30 - Email Chain re Engine Investigation
	207		2009.02.02 - Email Chain re: West IR Data
	208	(ID)	2009.02.03 - Email Chain re Accident Investigation
ŀ	209		2009.03.04 - Email re: West Engine Test Run
<u> </u>	210	(ID)	2009.03.05 - Email Chain re GPECS Involvement in Investigation
	211	()	2009.03.13 - Email re Accident Fuel System Examination
	212	(ID)	2009.03.25 - Email Chain re Accident Investigation
	213	(-2)	2009.03.26 - Email re: T-Fitting and Check Valve
-	214	(ID)	2009.03.27 - Email Chain re Accident Investigation
Ĺ	217	(10)	2007.03.27 Dinair Chain to Accident Investigation

г		(77)	2000 05 12 T 11 CT 1 1 1 1 1 1 1 1 1 1	
	215	(ID)	2009.05.13 - Email Chain re Accident Investigation	
	216	(ID)	2009.05.21 - Email Chain re Disposition of Accident Engine	
ļ	217	(ID)	2010.07.26 - Email Chain re Draft NTSB Factual Report	
-	218	(ID)	Sharkey's Notes from Inspection	
-	219	(ID)	West Engine Service and Maintenance Records	
	220	(ID)	2009.01.29 - Email Chain re: West Investigation	
}	221	(ID)	West ECU January 2009 Incident Recorder Download	
].	222	(ID)	2009.10.07 - Email Chain re Status of West Investigation	
	223	(ID)	2009.10.05 - Email re: Status of West Investigation	
-	224		2009.01.15 - Bell Flight Safety Mishap Report	
	225		2009.05.29 - GPECS West Repair Report	
-	226		West 2008 Flight Time Records	
	227		West 35A System Training Certificate from GPECS	
	228		Helicopter Bill of Sale to Speedway	
	229	(ID)	Morelia Incident Bell Preliominary Mishap Notification	
	230	(ID)	Morelia Incident Bell Helicopter Accident Investigation Record	علات
	231	(ID)	Morelia Incident Bell Notes of Interview with Pilot	Solve
ļ	232	(ID)	Morelia Incident ECU and IR Download	2349
ļ	233	(ID)	Morelia Incident Summary of Test Cell Run	,
	234	(ID)	Morelia Incident Bell Preliominary Mishap Notification Morelia Incident Bell Helicopter Accident Investigation Record Morelia Incident Bell Notes of Interview with Pilot Morelia Incident ECU and IR Download Morelia Incident Summary of Test Cell Run Morelia Incident Final Acceptance Test Data page 5 of 8 10 Strict Morelia Incident IR Download	Ken 9/12/
	235	(ID)	Morelia Incident IR Download	3365A
ļ	236	(ID)	Morelia Incident 2006.04.28 Email Chain	
	237	(ID)	Morelia Incident 2006.06.01 Email Chain	
	238	(ID)	Morelia Incident 2006.06.13 Chain	
	239	(ID)	Decatur Incident Bell Helicopter Accident Investigation Record	
	240	(ID)	2010.01.05 - Email Chain re: Pilot Statement in Decatur Incident	
	241	(ID)	Decatur Incident Rolls-Royce Engine Investigation Report	
ļ	242	(ID)	Decatur Incident Statement of Party Representatives	
	243	(ID)	India Incident Bell Final Investigation Report	
	244	(ID)	India Incident Bell and Rolls-Royce Answers to DGCA Questions	
	245	(ID)	India Incident Rolls-Royce Engine Investigation Report	
	246	(ID)	India Incident Bell Factual Observations	
	247	(ID)	India Incident 2006.08.02 Email Chain	
9117	248	(XK ()	India Incident Bell Response to DGCA Fax Subject to Reduction	
	249	(ID)	Bell 407 Manufacturer's Data re FADEC Excerpts	
	250	(ID)	ASB 407-03-60	
	251	(ID)	ASB 407-04-62	
	252	(ID)	ASB 407-96-2	
	253	(ID)	ASB 407-96-5	
	254	(ID)	ASB 407-96-6	
	255	(ID)	ASB 407-97-8	
	256	(ID)	ASB 407-99-31	
	257	(ID)	Bell Information Letter 407-03-71	
	2.50	~777~4	I I' I 11 - 1 2006 00 14 Fee 1 Chair as Incident December I asia	11- (11)
4117	258 259	(SPEX)	India Incident 2006.08.14 Email Chain re Incident Recorder Logic Subjection India Incident 2006.08.14 Email Chain	ct to reduction

260	(ID)	India Incident 2006.09.01 Email re Accident Profile
261	(ID)	India Incident 2006.10.30 Letter from Indian Government
262	(ID)	India Incident 2006.12.13 Letter from Indian Government
263		India Incident 2006.12.21 Email Chain re FADEC Reliability
	(ID)	Information
264	(ID)	India Incident 2007.03.01 Email Chain
265	(ID)	India Incident 2008.07.23 Letter from Indian Government
266	(ID)	Photograph of West Helicopter Particle Separator
267	(ID)	Castle Air Incident Bell Report
268	(ID)	Elipiu Incident Bell Report
269	(ID)	PHI Incident Bell File
270	(ID)	Forest Service Incident Bell File
271	(ID)	Irwin Incident Bell Preliminary Report
271A	(ID)	Irwin Incident Bell Preliminary Report RD
272	(ID)	Taji Incident Bell Preliminary Report
272A	(ID)	Taji Incident Bell Preliminary Report RD
273	(ID)	Tal Afar Incident Bell Aircraft Incident Notification Report
273A	(ID)	Tal Afar Incident Bell Aircraft Incident Notification Report RD
274	(ID)	Tal Afar Incident Bell Flight Safety Mishap Report
274A	(ID)	Tal Afar Incident Bell Flight Safety Mishap Report RD
275	(ID)	Kandahar Incident Bell Aircraft Mishap Notification
275A	(ID)	Kandahar Incident Bell Aircraft Mishap Notification RD
276	(ID)	Kandahar Incident Bell Safety Mishap Report
276A	(ID)	Kandahar Incident Bell Safety Mishap Report RD
277	(ID)	2009.01.28 - Email Chain re: Bell Coordination on Overspeed
278	(ID)	2011.04.07 - Email Chain re: 407 FADEC
279	(ID)	2009.05.21 - Email Chain re: 35R+ Faults
280	(ID)	2009.06.15 - Email Chain re: 35R+ Faults
281		1998.03.09 - Rolls Royce Presentation on Development of
	(ID)	Reversionary Mode
282	(ID)	2001.02.01 - Rolls Royce 250-C47B PSSHAC
283	(ID)	1997.09.02 - Bell/Allison Coordination Memo re: 5.201 Software
284	(ID)	Bell 407-960-011 Rev. D dated 09.08.1997
285	(ID)	Rolls-Royce EDR 18623 Safety/Hazard Analysis Report
286	(ID)	1998.11.20 - Bell Memo to File re: Visit to Chandler
287	(ID)	Jacksonville Incident Rolls-Royce Status Report
288	(ID)	1998 Rolls-Royce FADEC Reliability Update
289	(ID)	Bell Untitled List of Incidents
290	(ID)	GPECS ATP and ESS Procedures
291	(ID)	GPECS Standard Procedure re Nonconforming Material
292	(ID)	GPECS Procedure re: Test Equipment Control and Calibration
293	(ID)	Service Bulletin 73-32 re PLA and MV Potentiometers
294	(ID)	CEB 73-6011
295	(ID)	PMI 10003
296	(ID)	Component Maintenance Manual for 35A ECU 1997

219	297		PMI 10015 re Power Supply Distribution
417	298	(ID)	PSIL re OSPS Design Improvement
	299	(ID)	CEB 73-6048
	300	(ID)	Service Bulleting 73-1 re 35A to 35R Conversion
	301	(ID)	2009.05.13 - Email Chain re: West Accident, GPECS Data Review
	302	(ID)	Purchase Agreement between Rolls-Royce and GPECS
	303	(ID)	GPECS Documents re: Transfer of Accident HMU and ECU to Arrow
	304		West HMU GPECS Short Report
	305	(ID)	West ECU June 2009 ESS Test Results
	306		West ECU June 2009 ATP Test Results
, . [307		West ECU GPECS Short Report
G/ - V [308	(DEA),	FMECA Vol. I re 35A 250-C47B, 1998 man se super wird
`` \	309		CEB 73-6015 Rev. 2
	310	(ID)	CEB 73-6017 Rev. 2
	311	(ID)	CEB 73-6014 Rev. 3
	312	(ID)	GPECS Component Maintenance Manual re HMU
	313	(ID)	GPECS Component Maintenance Manual re: 35A HMU Rev. 1
_	314	(ID)	ECP 99-025 Supp. A re 35A
	315	(ID)	West ECU June 2009 ATP Results
	316	(ID)	CEB 73-6022 Rev. 4
	317	(ID)	NTSB Factual Report for West Incident - Reducted . So leve
	318	(ID)	Bow Police Dept. Incident Report re: West Accident
	319	(ID)	Product Support Agreement between Rolls-Royce and GPECS
	320	(ID)	West ECU June 2009 ESS Test Results
	321	1	West ECU January 2009 Download 1
	322		West ECU January 2009 Download 2
	323		2009.01.05 - GPECS Field Event Report on West Incident
	324	(ID)	West Incident GPECS Repair Report E12654
	325		West ECU June 2009 GPECS Test Instructions
-	326	(ID)	West ECU September 2003 GPECS NCMR Log
	327	(ID)	West ECU September 2003 GPECS NCMR Report 1
	328	(ID)	West ECU September 2003 GPECS NCMR Report 2
	329		West ECU September 2003 GPECS Final Assembly Inspection
		(ID)	Control Card
	330	(ID)	PSIL re OSPS Design Improvement, Kiowa
	330A	(ID)	PSIL re OSPS Design Improvement, Kiowa RD
	331	(ID)	PMI 10030 re Software Upgrade
	332	(ID)	West ECU September 2003 GPECS NCMR Report 3
	333	(ID)	35R Primary Governor Block Diagram
	334	(ID)	Relight Flow vs. Ambient Pressure Graph
-	335	(ID)	GPECS Certification Plan for the 35R Software Upgrade in C47B
	336	(ID)	IFM 10-009
	337	(ID)	FMECA Vol. I re 35R 250-C47B, 2008
<u> </u>		+ ' /	· · · · · · · · · · · · · · · · · · ·
	338	(ID)	GPECS 35A/R HMU for C47B/M

a cetru

*317(9) Redacted resion admitted

Г	240	(ID)	Rolls Royce Reversionary Governor Program Presentation
-	340	(ID)	Rucker Incident IR Data
-	341	(ID)	Rucker Incident IX Data Rucker Incident GPECS ECU Short Report
+	342	(ID)	
-	342A	(ID)	Rucker Incident GPECS ECU Short Report RD
	343	(ID)	OH-58D Incident Investigation Summary
-	343A	(ID)	OH-58D Incident Investigation Summary RD
-	344	(ID)	West ECU June 2009 ATP Test Results
	345	(ID)	West ECU June 2009 ESS Summary
9/10	346		West ECU June 2009 Repeat Test 13 Results
1	347	(ID)	SRS re 35R, C-213 Rev. J
L	348	(ID)	GPECS Model 250 First Network Global Conference Presentation
	349	(ID)	2010.06.02 - Email Chain re: EMC-35 Tantalum Capacitor Changes
	350	(ID)	2010.03.02 - Email Chain re: EMC-35 Tantalum Capacitor Changes
	350A		2010.03.02 - Email Chain re: EMC-35 Tantalum Capacitor Changes
		(ID)	RD
	351	(ID)	GPECS CLRP re ECU Power Supply
	352	(ID)	2008.12.18 - Email Chain re: FBI Houston Accident
	353	(ID)	GPECS CLRP re ECU Power Supply
	354	(ID)	Service Bulletin 73-4 DRAFT re OSPS
	355	(ID)	Service Bulletin 73-X DRAFT re OSPS
	356	(ID)	IFM 07-004 1
L	357	(ID)	IFM 07-004 2
Ĺ	357A	(ID)	IFM 07-004 2 RD
	358	(ID)_	2007.02.20 Email Chain re: FMECA Revision
	358A	(ID)	2007.02.20 Email Chain re: FMECA Revision RD
-	359	(ID)_	IFM 07-008
	360	(ID)	IFM 07-019
	361	(ID)	IFM 07-024 1
a/20	362(A))HQ)	IFM 07-0242 Subject to redaction
~, [(ID)	IFM 07-029A
	364	(ID)	EMC 35 Model 250 2008 Improvements
	365	(ID)	IFM 07-032 2007.11.26
	366	(ID)	IFM 07-005
	367	(ID)	IFM 08-012
	368	(ID)	IFM 08-012A
	369	(ID)	IFM 08-014
	369A	(ID)	IFM 08-014 RD
	370	(ID)	IFM 08-023
	371	(ID)	IFM 08-023 rev. A
	372	(ID)	IFM 08-027
	373	(ID)	IFM 08-027 R1
	374	(ID)	IFM 08-009
	374A	(ID)	IFM 08-009 RD
[375	(ID)	IFM 09-001
	376	(ID)	IFM 09-022

_	277	(ID)	IFM 09-028
-	377	(ID)	IFM 09-028 IFM 09-030
-	378	(ID)	
	379	(ID)	IFM 09-025
919	380	(XXX)	IFM 06-025
_	381	(ID)	IFM 06-022
-	382	(ID)	IFM Attachment based on Nov. 14, 2006
L	383	(ID)	2009.08.06 EMC35R Investigation Status
_	384	(ID)	GPECS CLRP re Power Supply Ta Cap Upgrade
	385	(ID)	2009.01.23 GPECS Product Support Summary
_	385A	(ID)	2009.01.23 GPECS Product Support Summary RD
	386	(ID)	2007.02.07 35A ECU Design Analysis
	386A	(ID)	200702.07 35A ECU Design Analysis RD
	387	(ID)	GPECS Short Report re Power Supply Reliability Review
	388	(ID)	GPECS Short Report Summary re Tantalum Capacitor Alternative
	389	(ID)	PPRB Meeting Recap, Oct. 3, 2007
	390	(ID)	2010.09.08 Email Chain re: Capacitor Changes
	390A	(ID)	2010.09.08 Email Chain re: Capacitor Changes RD
	391	(ID)	2010.05.18 Email Chain re: Confirmed Ta Capacitor Failures
	391A	(ID)	2010.05.18 Email Chain re: Confirmed Ta Capacitor Failures RD
	392	(ID)	2010.05.13 Email Chain re: Implementation of Capacitor Change
	392A	(ID)	2010.05.13 Email Chain re: Implementation of Capacitor Change RD
	393	(ID)	2008.09.26 Email Chain re: Capacitor Change
	394	(ID)	2008.06.18 Email Chain re: Software Upgrade
	395	(ID)	2007.02.26 Email Chain re: FMECA Revisions
	395A	(ID)	2007.02.26 Email Chain re: FMECA Revisions RD
	396	(ID)	2007.01.26 Email Chain re IFM
	397	(ID)	Pannullo Recommendations re: 35A Capacitor
	398	(ID)	IFM 07-002
	399	(ID)	Kurt West - JBI Piloting Records
	400	(ID)	Kurt West 2009 Timecards
	401	(ID)	West 2009 Time Cards
	402	(ID)	West 2010 Time Cards
	403	(ID)	West 2011 Time Cards
	404	(ID)	West 2011 Time Cards
	405	(ID)	West 2012 Time Cards
	406	(ID)	West 2008-2009 Time Cards
	407	(ID)	Bell Helicopter Log and Technical Log for West Helicopter
	408	(ID)	Rolls Royce Maintenance and Inspection Records for West Engine
<u> </u>	409		JBI Documents for Incident Helicopter
	410		JBI Maintenance Records for Incident Helicopter
	411	(ID)	ASB 407-07-75
-	412		List of Optional Equipment on Incident Helicopter
,	413	(ID)	Incident Helicopter Registration
1 1.	414	(ID)	JBI Incident Helicopter Photographs 1
	415	(DBK)	JBI Incident Helicopter Photographs 2
-	112	رافت المراجع	1021 mercent reneopter r noto Brahm m

416		West Incident GPS Data	
417	(ID)	P. Inc.	_
	(ID)	JBI Incident Helicopter Photographs 3	_
418	(ID)	JBI Incident Helicopter Photographs 4	
419	(ID)	JBI Monthly Flight Summaries	_
420	(ID)	CEB Index 2010	
421	(ID)	2010.09.01 - Rolls-Royce Illustrated Parts Catalog	- (hun
422	(ID)	Rolls Royce C47 CSLTechnical Publications Index	
423	(ID)	CEB 73-6036 Rev. 1	
424	(ID)	CEB 73-6036 Rev. 2	
425	(ID)	CEB 73-6048 Rev. 4	
426	(ID)	CSL 6113	
427		2009.09.01 - Rolls Royce Complete Operation and Maintenance	
		Manual	
428	(ID)	CSL 6113 Rev. 2	
429	(ID)	CSL 6118	
430		West Incident Rolls Royce Accident Report Closure	
431		2009.03.03 - Accident Investigation Attendees	
432	(ID)	ASB 407-07-75 Rev. B	
433		Typical FADEC Control System Diagram	
434	(ID)	NTSB Probable Cause Report for West Incident	
435	(ID)	2009.03.05 - Email Chain re West Incident Investigation	
436	(ID)	2009.05.05 - Email Chain re West Incident Investigation	
437		2009.01.21 - ECU download from West Helicopter	
438	(ID)	Test Emergency Fuel Shutdown Incident Recorder Plot	
439	(ID)	2009.03.05 - Email Chain re Bell 407 Efforts	
440	(ID)	2009.05.12 - Email from Newcomb re Bell 407 Helicopter	
441		2009.01.29 Email from Sharkey to Cox Re Engine Removal	
442		Photograph at Sharkeys 1	
443		Photograph at Sharkeys 2	
444		Photograph at Sharkeys 3	
445		Photograph at Sharkeys 4	
446		Photograph at Sharkeys 5	
447		Photograph at Sharkeys 6	
448		Photograph at Sharkeys 7	
449		Photograph at Sharkeys 8	
450		2009.01.29 Email from Sharkey to Cox Re Engine Removal	1
451		Photograph at Sharkeys 9	
452		Photograph at Sharkeys 10	
453		Photograph at Sharkeys 11	_
454		Photograph at Sharkeys 12	
455	+		
456		2009.01.29 Email from Sharkey to Cox Re Engine Removal	
		Photograph at Sharkeys 13	_
457	1	Photograph at Sharkeys 14	_
458	(ID)	Photograph at Sharkeys 15	\dashv
459	(ID)	2009.03.04 - Email from Cox re JBI Investigation New Hampshire	1

12

460	(ID)	2009.03.27 - Email Chain re Bell 407
461		2001.09.15 - 250-C47B Engine Description and Operation
462	(ID)	2002.02.07 - Rolls Royce Safety Analysis Field Data Update
463		2003.02.05 - Rolls Royce Model 250 Safety Review Board
	(ID)	Presentation
463A	•	2003.02.05 - Rolls Royce Model 250 Safety Review Board
	(ID)	Presentation RD
464	(ID)	2009.03.25 - Email Chain re JBI 407
9/16 465 6	(XX ()	2009.04.01 - Email Chain re JBI 407
466	(ID)	2009.05.13 - Email Chain re JBI 407 Incident, GPECS Data Review
467	(ID)	West Impeller Photograph 1
468		West Impeller Blade Photograph
469	(ID)	West Impeller Photograph 2
470		Photo of West Accident Scene 1
471		Photo of West Accident Scene 2
472		Photo of West Accident Scene 3
473		Photo of West Accident Scene 4
474		Photo of West Accident Scene 5
475		Photo of West Accident Scene 6
476		Photo of Cockpit Post-Accident
477	(ID)	Long Term Agreement Between Rolls Royce and Bell
478		West ECU September 2003 ATP Test Data
479	(ID)	Morelia Incident Florida Complaint
480	(ID)	Long Term Agreement Between Rolls Royce and Chandler
481	(ID)	Morelia Incident Rolls Royce Engine Investigation
482	(ID)	Decatur Incident Incident Recorder Data
~ 483	XX	Decatur Incident Impeller Photographs
484	(ID)	Decatur Incident NTSB Factual Report
485	(ID)	Virgina Incident Rolls Royce File
486	(ID)	Castle Air Incident Rolls Royce Accident Investigation Report
487 -	(ID)	PHI Incident Rolls Royce File
487A	(ID)	PHI Incident Rolls-Royce File RD
487B		PHI Incident IFM 03-014
488	(ID)	2005.01.28 - Letter from Rolls Royce to NTSB re 35R
489	(ID)	M250 Basic Unplanned Failures of Series IV ECU
490	(ID)	CEB 73-6048 Rev. 5
491	(ID)	CSL 6117
492	(ID)	CSL 6125 Rev. 3
493	(ID)	PMI I0026
494	(ID)	EPC 08-034
495		GPECS April 2003 FADEC System Presentation
496		Model 250 Program Overview
497	(ID)	Irwin Incident Rolls Royce File
497A	(ID)	Irwin Incident Rolls Royce File RD
498	(ID)	Irwin Incident Rolls Royce Red Top Closure Report

498A	(ID)	Irwin Incident Rolls Royce Red Top Closure Report RD
499	(ID)	Irwin Incident Rolls Royce Internal Memorandum
499A	(ID)	Irwin Incident Rolls Royce Red Top Closure Report RD
500	(ID)	Irwin Incident Rolls Royce Accident Investigation Report
500A	(ID)	Irwin Incident Rolls Royce Accident Investigation Report RD
501	(ID)	Taji Incident Rolls Royce Red Top Closure Report
501A	(ID)	Taji Incident Rolls Royce Red Top Closure Report RD
502	(ID)	Colorado Incident McBrine Summary
503	(ID)	Kandahar Incident Rolls Royce Engine Investigation Report
503A	(ID)	Kandahar Incident Rolls Royce Engine Investigation Report RD
504	(ID)	Kandahar Incident GPECS Short Report
504A	(ID)	Kandahar Incident GPECS Short Report RD
505	(ID)	Kandahar Rolls Royce Accident Report Closure
505A	(ID)	Kandahar Rolls Royce Accident Report Closure RD
506	(ID)	Kandahar Incident Rolls Royce Component Investigation Report
506A	(ID)	Kandahar Incident Rolls Royce Component Investigation Report RD
507	(ID)	Rucker Incident Rolls Royce Report Closure
507A	(ID)	Rucker Incident Rolls Royce Report Closure RD
508	(ID)	Tal-Afar Incident Rolls Royce Report Closure
508A	(ID)	Tal-Afar Incident Rolls Royce Report Closure RD
509	(ID)	Rucker Incident Minutes of Rolls Royce PPSRB
509A	(ID)	Rucker Incident Minutes of Rolls Royce PPSRB RD
510	(ID)	Rucker Incident 12.2006 PPSRB Presentation
510A	(ID)	Rucker Incident 12.2006 PPSRB Presentation RD
511	(ID)	2009.02.04 - Rolls Royce PPSRB Presentation
511A	(ID)	2009.02.04 Rolls Royce PPSRB Presentation RD
512	(ID)	2009.07.31 - Rolls Royce PPSRB Presentation
512A	(ID)	2009.07.31 - Rolls Royce PPSRB Presentation RD
513	(ID)	Rolls Royce Model 250 Safety Review Board Controls Presentation
513A		Rolls Royce Model 250 Safety Review Board Controls PResentation
	(ID)	RD
514	(ID)	2007.03.30 - Rolls Royce PPSRB Presentation
515		2003.05.01 - Rolls Royce Special Site Safety Review Board
	(ID)	Presentation
515A		2003.05.01 Rolls Royce Special Site Safety Review Board Presentation
	(ID)	RD
516	(ID)	2009.12.04 - Rolls Royce PPSRB Presentation
516A	(ID)	2009.12.04 - Rolls Royce PPSRB Presentation RD
517	(ID)	IFM 07-037
518	(ID)	Pie Chart re FOSSA Trip Rates
519	(ID)	Capacitor Failure Rate and FOSSA Rate Charts
520	(ID)	Tantalum and SMT Capacitor Summary Presentation July 2008
520A	(ID)	Tantalum and SMT Capacitor Summary Presntation July 2008 RD
521	(ID)	LOTC and Ta Capacitor Chart
521A	(ID)	LOTC and Ta Capacitor Chart RD

522	(ID)	Rucker Incident Rolls Royce Red Top Closure Report
522A	(ID)	Rucker Incident Rolls Royce Red Top Closure Report RD
523	(ID)	2007.07.30 - Email Chain re LOTC X Factor
524	(ID)	2007.09.19 - Email Chain re 35A Tantalum Capacitor Issue
524A	(ID)	2007.09.19 Email Chain re 35A Tantalum Capacitor Issue RD
525	(ID)	2008.07.17 - Email Chain re FADEC Capacitor Mod Incorporation
526	(ID)	2007.11.27 - Email re Tantalum Capacitors and SMT Capacitors
527	(ID)	Rolls Royce 250 ECU May 2008 Status Presentation
527A	(ID)	Rolls Royce 250 ECU May 2008 Status Presentation RD
528	(ID)	IFM 07-028
528A	(ID)	IFM 07-028 RD
529	(ID)	IFM 07-020
530	(ID)	IFM 07-032 2007.11.5
531	(ID)	IFM 07-027
532	(ID)	IFM 07-029
533	(ID)	Stewart Incident - Email Chain re FADEC Hard Fault Incidents
533A	(ID)	Stewart Incident - Email Chain re FADEC Hard Fault Incidents RD
533B		Stewart Incident - Email Chain re FADEC Hard Fault Incidents -
9/18/13		Ronan Ex. 16 RD
534	(ID)	250-C47B Rolls Royce Control System Description Document
535	(ID)	Rolls Royce HMU Schematic
536	(ID)	PHI Incident - 2003.07.14 Email Chain re FAA Action
537		2004.30.30 - Rolls Royce CSL re: FADEC Operation and Maintenance
		Guidelines
538	(ID)	2006.12.08 - Email Chain re ECU Capacitor Issues
538A	(ID)	2006.12.08 - Email Chain re ECU Capacitor Issues RD
539	(ID)	Red Top 2006-163 ECU Capacitor Matrix Slide
540	(ID)	Irwin Incident - Rolls Royce Accident Report Closure
540A	(ID)	Irwin Incident - Rolls Royce Accident Report Closure RD
540B		Irwin Incident – Rolls Royce Accident Report Closure – Ronan Ex. 3
913	(3)	RD
541	(ID)	Rucker Incident - Rolls Royce Potential Hazard Report
541A	(ID)	Rucker Incident - Rolls Royce Potential Hazard Report RD
542	(ID)	Rucker Incident - GPECS Report Number E9135
542A	(ID)	Rucker Incident - GPECS Report Number E9135 RD
543	(ID)	Rolls Royce Model 250 ECU Genealogy
544		250-C47B Operation and Maintenance Manual (Sep. 2005)
545	(ID)	Agenda for April 2004 Reversionary Governor Meeting
546	(ID)	2008.12.09 - Email Chain re Proposed 47M Software for Overspeed
547	(ID)	CEB 73-6026
548	(ID)	Rolls Royce Reversionary Governor Overview Presentation
549		2006.09.06 - Rolls Royce C47B Commercial Turboshaft Engine
550	(ID)	CEB 73-6036 - 2004.06.11 Email Chain re Compliance
551	(ID)	PHI Incident - 2003.05.14 Email Chain re Incident Information
552	(ID)	IFM 07-039

552A B (ID) IFM 07-030 DD (10) IFM 07-039 RD subject to a reduction : idaction Rucker Incident - Rolls Royce Presentation on ECU Capacitor Change (ID) Rucker Incident - Rolls Royce Presentation on ECU Capacitor Change 553A (ID) 554 EMC-35A MRO ECU Reliability Chart (ID) 2009.09.09 - Email Chain re Tantalum Capacitor Meeting Action Items 555 (ID) 556 (ID) Rolls Royce Reversionary Governor Reliability Analysis 557 (ID) IFM 08-003 EMC-35A Tantalum Capacitor Failure Summary Chart 558 (ID) 559 Irwin Incident - GPECS Short Report on ECU (ID) 919 559A (ID) Irwin Incident - GPECS Short Report on ECU RD 560 (ID) 2006.12.08 - Email Chain re OS Counter 2007.08.13 - Email Chain re 35R and 35A Safety 561 (ID) Rolls Royce 2007 Trip to GPECS Observations and Impressions 562 (ID) Rolls Royce 2007 Trip to GPECS Observations and Impressions RD 562A (ID) Tantalum & SMT Capacitor July 2008 Summary Presentation 563 (ID) 563A (ID) Tantalum & SMT Capacitor July 2008 Summary Presentation RD 564 (ID) Rolls Royce EDR 22906 Rolls Royce EDR 22906 RD 564A (ID) Rolls Royce April 2008 Model 250 Tantalum Capacitor Issue 565 Presentation (ID) Rolls Royce April 2008 Model 250 Tantalum Capacitor Issue 565A (ID) Presentation RD IFM OH58-RR-180 566 (ID) IFM OH58-RR-180 RD 566A (ID) Rucker Incident - Rolls Royce ECU Capacitor Failure Presentation 567 (ID) Rucker Incident - Rolls Royce ECU Capacitor Failure Presentation RD 567A (ID) Rolls Royce EMC-35A 35R Power Supply PIP Design Analysis 568 (ID) Summary 1 569 (ID) Rolls Royce EMC-35A 35R Power Supply PIP Design Analysis 2 570 Rucker Incident - Rolls Royce Presentation with Answers to Questions (ID) 570A Rucker Incident - Rolls Royce Presentation with Answers to Questions (ID) RD 571 (ID) IFM OH58-RR-154 571A (ID) IFM OH58-RR-154 RD 572 2006.11.21 Email Chain re C47M Accomplishment Data Changes (ID) 573 IFM OH58-RR-160 (ID) 573A IFM OH58-RR-160 RD (ID) Rolls Royce July 2008 CLS Meeting Ta Capacitor Presentation 574 (ID) 575 (ID) EMC-35A Tantalum Capacitor Failures Summary Chart 2008.07.17 EMC-35 OSPS Reliability Design Improvement Presentation 576 (ID) 2008.09.03 - Email Chain re: FOSSA Questions 577 (ID) 578 (ID) 2008.05.15 Email Chain re: Ta Capacitors Substantiation Paper 579 (ID) 2008.06.03 Email Chain re: Ta Capacitor Failure Rates 579A 2008.06.03 Email Chain re: Ta Capacitor Failure Rates RD (ID)

580100 Reducted resion GPECS Short Report re Power Supply Transient Testing 1/9 580 2008.09.09 - Email Chain re: Tantalum Capacitor Meeting Action 581 (ID) 581A 2008.09.09 - Email Chain re: Tantalum Capacitor Meeting Action (ID) Items RD 2008.09.09 Email Chain re: Capacitor Changes 582 (ID) 2008.09.09 Email Chain re: Capacitor Changes RD 582A (ID) Rolls-Royce EDR 22906 re Tantalum Capacitor Change 583 (ID) 584 (ID) IFM 07-035 IFM 07-035 RD 584A (ID) Rolls-Royce Presentation re: Ta Capacitor 585 (ID) IFM 07-022 586 (ID) GPECS Short Report on 35A False Overspeed Trip Hazard Analysis 587 (ID) Reassessment (ID) 2008.08.25 Email re: Ta Capacitor Failures 588 2008.11.14 Email Chain re: SMT Capacitors 589 (ID) 590 Rolls Royce November 2008 SMT Capacitor Change Presentation (ID) 590A (ID) Rolls Royce November 2008 SMT Capacitor Change Presentation RD 591 IFM 08-017 1 (ID) 592 Rolls-Royce Comments on GPECS Substantiation for OS Change (ID) 593 (ID) RRC Safety Board Project re Capacitor Change 594 (ID) Revised Hazard/Safety Calculations R-2121 Rev.A 595 IFM 08-017 2 (ai)2003.12.05 - Optional Equipment Installed on West Helicopter 596 597 Sharkey Inspection Report (XXI) 4 111 598 Lufkin Incident - GPECS Short Report (ID) 9/2 599 Elipiu Incident - GPECS Short Report TEA 4/2 P 600 (NO) Elipiu Incident - GPECS Short Report Rev. A Elipiu Incident - GPECS Short Report Additional Analysis a 126 601 **(DX)** 602 (ID) Castle Air Incident - GPECS Short Report on HMU 603 (ID) Castle Air Incident - GPECS Short Report on ECU 604 Irwin Incident - GPECS Short Report on HMU (ID) 604A (ID) Irwin Incident - GPECS Short Report on HMU RD 605 (ID) Irwin Incident - GPECS Short Report on ECU Irwin Incident - GPECS Short Report on ECU RD 605A (ID) Irwin Incident - GPECS Short Report on ECU - Ronan Ex. 2 RD 9/23 605B (**XX**) 606 PHI Incident GPECS HMU Short Report (ID) 607 (10)PHI Incident GPECS ECU Short Report 607A (IR) PHI Incident GPECS ECU Short Report RD Taji Incident - GPECS Short Report on HMU Rev. 1 608 (ID) 608A (ID) Taji Incident - GPECS Short Report on HMU Rev. 1RD 609 Taji Incident - GPECS Short Report on HMU (ID) 609A (ID) Taji Incident - GPECS Short Report on HMU RD 610 Bragg Incident - GPECS Short Report on ECU (ID) 610A Bragg Incident - GPECS Short Report on ECU RD (ID)

	611	(ID)	GPECS Short Report re Failure Mode Analysis for 35R Supplement 4
	612	(ID)	CSL 6034
	612A	(ID)	CSL 6034 RD
	613	(ID)	PSIL 09-001 Technical Publications Internal Review
	614	(ID)	PMI I0030
	615	(ID)	Fault Isolation Manual for Bell 407
	616	(ID)	PSIL 09-001
	617	(ID)	PSIL 09-002
qilo	618 B	DET	Loma Bonita Incident GPECS Short Report subject to redach
,,, [618A	(ID)	Loma Bonita Incident GPES Short Report
	619	(ID)	Loma Bonita Incident - Email re Investigation Questions
	620	(ID)	Loma Bonita Incident - Incident Recorder Data 1
Γ	621	(ID)	Loma Bonita Incident - Incident Recorder Data 2
	622	(ID)	Loma Bonita Incident Recorder Data 3
	623	(ID)	Loma Bonita Incident - Incident Recorder Snapshot Data
	624	(ID)	Loma Bonita Incident Recorder Data 4
	625	(ID)	Loma Bonita Incident - GPECS Investigation Summary
	626	(ID)	Loma Bonita Incident - Letter from Millar to Kemet
	627	(ID)	2013.02.01 Letter from D. Wright re Coloncs
 #	628 A	(342)	GPECS SRS for 35A Rev. C
`	629	(ID)	West Airman File
	630	(ID)	Foundation Medical Partners Receipt 1
	631	(ID)	West Certificate of Recognition from Bell Training Academy
	632	(ID)	West Certificate of Flight from Bell Training Academy
	633	(ID)	Bell 2012 Flight Training Record for West
	634		West ECU December 2008 Incident Recorder Data 2
	635	(ID)	West ECU December 2008 Incident Recorder Data 1
	636	(ID)	2009.02.05 - Email Chain re Accident Investigation
-	637	(ID)	2009.02.27 - Email from Whitson re Incident Helicopter
	638	(ID)	2009.03.04 - Email from Sharkey re Incident Helicopter Damage
	639	(ID)	2009.05.12 Email from Sharkey re Inspection of Fuel System
	640	(ID)	West Pilot License
	641		Cockpit Photograph
	642	(ID)	Cockpit Photograph 2
	643		Incident Helicopter Helicopter Standard Airworthiness Certificate
	644		Incident Helicopter Registration
	645		Photograph of Cockpit Lamps 1
	646		Photograph of Cockpit Lamps 2
	647	(ID)	2012 West Airman Competency and Proficiency Check
	648	(ID)	CEB 73-6052
	649	(ID)	Drukteinis Examination Notes
	650	(ID)	West FAA Medical File
	651	(ID)	Drukteinis Testing Results
	652	(ID)	HMU Schematic - Metering Unit
⊢	653	(ID)	West ECU August 2012 ATP Test Data

x. 14	654 (ID) 655 (ID) 656
x. 14	656
x. 14	
	657
	658 (ID)
	660 (ID)
	661
	662 (ID)
	663 (ID)
	664 (ID)
	665 (ID)
	666 (ID)
	667 (ID)
	668 (ID)
	669 (ID)
	670 (ID)
	671 (ID)
	672
	673
	674
	675
	676
	677
	678
	679
n	680
	681 (ID)
	682 (ID)
	683 (ID)
	683A (ID)
	684 (ID)
	685 (ID)
	686 (ID)
	687 (ID)
+ to Reduction	
1 16 years 100	
onan	
V-1411	1 2
	696 (ID)
	697 (ID)
t to Cec	688 689 (ID) 690 (ID) 691 (ID) 692 (ID) 693 (ID) 694 (ID) 695

	699	(ID)	DHHS Life Expectancy Table	
	700	(ID)	Slane Report - Slane Ex. 9	
	701	(ID)	ECU Inspection Photograph 1	
	702	(ID)	ECU Inspection Photograph 2	
	703	(ID)	ECU Inspection Photograph 3	
	704	(ID)	ECU Inspection Photograph 4	
	705	(ID)	ECU Inspection Photograph 5	
	706	(ID)	ECU Inspection Photograph 6	
	707	(ID)	Trauma Center Supervisory Notes	
	708	(ID)	CEB 73-6032	
919	709 🗸	X	EMC-35A Color Drawing	23)
•	710	(ID)	Bell 407 FADEC System Training Class , 7 10(x) - (overpage +	12 47 j
	711	(ID)	Decatur Incident 2010.02.23 Email Chain	
	712	(ID)	Decatur Incident NTSB Preliminary Report	_
-156a 3	712 713 a 714	(Ha)	Decatur Incident Video	
11.77.77	714	(ID)	Slane Report - Slane Ex. 1	
1.10	715	(ID)	2013.04.18 McBrine Email – Slane Ex. 7	
	716	(ID)	Rucker Incident – Slane Ex. 12	
	717	(ID)	Polar First Excerpts	=
9111	728	(1380)	West Test Emergency Shutdown Comparative IR Plot with Snapshots	_
,,	729	(1D)	IR Data from Decatur TX Flameout	
9111	730		KW TES Comparison	
_	731	(ID)	West Decatur Comparative IR plot	
913	732		West Decatur Comparative IR plot with snapshots	

Respectfully Submitted,

KURT WEST

By His Attorneys

/s/ Joan A. Lukey

Joan A. Lukey, N.H. Bar ID #16246
Justin J. Wolosz, admitted pro hac vice
Jesse M. Boodoo, admitted pro hac vice
Ropes & Gray LLP
Prudential Tower
800 Boylston Street
Boston, MA 02199-3600
(617) 951-7000
joan.lukey@ropesgray.com
jesse.boodoo@ropesgray.com

Date: September 9, 2013

UNITED STATES DISTRICT COURT DISTRICT OF NEW HAMPSHIRE

4	Jest

Bell Helicopher Textron Inc

Case # 10-CV-214 JL 5

EXHIBITS

OFFERED BY: Pla	untiff
NUMBER/LETTER	DESCRIPTION
	Receipt
9111 725 x e	Return Chack, Ceceipt
91m	Receipt
7276	
719	Nashua West Adult Consolidated Report
721	Dortmouth Hitchock Consolidated Report
נפר	12/16/09 Lakey Consolidated Report
72200	Supplemental Report - Laker
734(20)	Sharten email Re: speedway Arrabian Demo Model of Bell 407 (will be substituted @ end Demo Model of Bell 407 (offmal with a photo
	Helicopter Whoels
736 (12)	Planon Chamber (19 physiad exhibit
737 (10)	MUSANOSA
P 312(a)	of Blow-up - entered by A's
P720	Concord Hospital Consolidated Record

USDCNH-25 (2-96)